

From: [Moore, Gary](#)
To: ["jasonstephens@suddenlinkmail.com"](mailto:jasonstephens@suddenlinkmail.com)
Subject: FJ Doyle Salvage Site
Date: Friday, May 04, 2018 11:17:33 AM
Attachments: [03.29.18 FJDoyle_20180329-mgkg.xlsx](#)
[1998.08 SSI Report Isopleth Concentration Map.pdf](#)

Jason:

I wanted to pass along some information to you on the site. I am in the preliminary stages of determining what we need to do and am checking to see what we have as possible disposal locations for non-TSCA/non-haz waste materials. We just completed additional assessment sampling this week to determine the extent of contamination and confirm historical analyses. Attached are the historical data. I am also providing a map which may be useful.

I need to find out the following:

1. Permit Information
2. Landfill Name and Physical Address
3. Acceptance Criteria
4. Since this will be classified as a CERCLA "Superfund" Waste, you guys will have to request EPA CERCLA Approval (I will have to get you the details but the person at EPA that does this is Wilkin "Ron" Shannon; (b) (6); shannon.wilkin@epa.gov). I currently have a call into him.

thanks

Gary W. Moore (6SF-ER)
Federal On-Scene Coordinator
U.S EPA Region 6
1445 Ross Ave, Suite 1200
Dallas, TX 75202-2733
Cell: 214.789.1627
moore.gary@epa.gov